

# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213

**Photo - 1**

Front of Risk



**Photo - 2**

garage side





# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 3

heavy charring on front upper siding,  
soffit



Photo - 4

rear of risk



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213

**Photo - 5**

dwelling side



**Photo - 6**

front-opposite view





# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 7

alleged point of origin



Photo - 8

garage roof opened by FD



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 9

smoke in garage, no structural damage except roof



Photo - 11

off kitchen/breakfast room-double door onto deck



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 10

kitchen/breakfast room area



Photo - 12

kitchen/breakfast room



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 13

living room



Photo - 14

living room-front door entry



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 15

living room ceiling



Photo - 16

living room to hallway



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 17

bedroom 1-door was closed-smoke damage, minro structural (finish sheetrock)




Photo - 18

smoke damage to clothes in bedroom 1



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 19

hallway



Photo - 20

rear office/game room



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 21

rear office/game room



Photo - 22

hardwood flooring-gameroom



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 23

bedroom 2



Photo - 24

bedroom 2



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213

Photo - 25

bedroom 2



Photo - 26

bathroom





# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 27

bathroom



Photo - 28

stairway to finished basement-off  
kitchen area



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213

Photo - 29

utility room-heavy smoke and water




Photo - 30

utility room





# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213

Photo - 31

entry to family room-heavy smoke and water



Photo - 32

family room





# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 33

pool room off family room



Photo - 34

floor in family room



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213




Photo - 35

master bedroom in basement



Photo - 36

clothing, water to carpeted floor,  
paneling and ceiling wet



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 37

ceiling



Photo - 38

storage closet, water damage to paneling



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 39

storage in basement-contents salvagable here



Photo - 40

bathroom in basement



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 41

ceiling in pool room



Photo - 42

rear deck charred



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 43

rear deck, siding, soffit and fascia.  
also, roof damage observed



Photo - 44

garage roof



# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213

Photo - 45

dwelling roof also opened



Photo - 46

heavy smoke around vents, chimney





# Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768  
Policy # 264841951  
Ins Claim # 66F318775-213



Photo - 47

close up