TO:

Landmark Committee

DATE: January 11, 2012

RE:

729 Jenifer Street


Upper, Side and Replacement of Decking Boards in Hot Tub Area

Enclosed are the pictures of the decks at 729 Jenifer Street and the decks on the two parcels of land on either side. Also included is a site plan where the decks were replaced.


The 729 pictures include before and after construction. The upper and side decks had not been repaired for 35 to 50 (or more) years. Previous to my ownership, they had been worked on several different times. Rotten boards and leakage in the lower unit made it necessary to replace.

From the pictures, you can see that the railings are identical to the ones replaced at 729 last year. Treated wood was used for the railings and composite gray wood grain decking was used for the decking that would match the siding.

Mayne Tiedler
Wayne Fiedler




729 JENNIFER STREET PART OF LOT 5, BLOCK 127, ORIGINAL PLAT OF MADISON





Jenkins Survey & Design, Inc. 245 Horizon Drive, Suite #108 Verona, Wisconsin 53593 608-848-5060

Wayne Fiedler 729 Jennifer St. Madison, Wisconsin 53703




729 Before Side Deck









Upper Peck

- Three different Types of railings.

- Two different types of deaking

- 7 different types
of roofing under
the decking


Before Upper Deck

Upper Deck After





Lower





Bruns







735 Potter