

Street Tree Report - Land Use Application

Page 2

SECTION 2 – STREET TREE INVENTORY AND CONSTRUCTION IMPACT

STREET TREE NUMBER	Tree Species (Common Name)	Trunk Diameter (DBH)	Canopy Spread (Ft)	Trunk/Roots: General Structure/Health/Condition	Removal (R) Requested by Applicant? (Yes or No) *Photos required*	Pruning by City Forestry requested (Yes or No). Note: Any Pruning must follow ANSI A300 Standards.	What are the impacts of proposed building? i.e., construction, staging, underground vaults, concrete pumps, scaffolding, new underground utilities, etc.	What are the earth retention impacts to the street trees?
1	Gleditsia triacanthos variety (honey locust)	5"	~8'	In grate	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION,, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
2	Ulmus variety (elm)	6"	~10'	In grate	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, STAGING, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
3	Gleditsia triacanthos variety (honey locust)	3"	~5'	In grate	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
4	Ulmus variety (elm)	10"	~18'	In grate	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
5	Ulmus variety (elm)	4"	~7'	In grate	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
6	Gleditsia triacanthos variety (honey locust)	6"	~18'	In gate, leader not straight	<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
7	Tilia cordata (linden)	8"	~14'	In grate	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND SCAFFOLDING	N/A
8	Gleditsia triacanthos variety (honey locust)	12"	~20'	In grate, some dieback	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND STAGING	N/A
9	Gymnocladus dioicus (kentucky coffee)	3"	n/a/	Dead	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND STAGING	N/A
10	Gleditsia triacanthos variety (honey locust)	3"	~5'	In grate, newly planted	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND STAGING	N/A

Street Tree Report - Land Use Application

Page 3

Please attach a **plan** of the proposed project site that includes street trees corresponding to the street tree listed in Section 2 of Street Tree Inventory.

Additional notes:

Inventory #11, the W. Mifflin Plaza or Philosopher's Grove trees were identified as one inventory item as they are all in the same general size, health, species and planting condition. Exceptions were listed in inventory line items 8-10.

Describe impacts and any mitigation actions employed:

With urban construction hardships, the Wisconsin History Center and team have identified the W. Mifflin Plaza (Philosopher's Grove) as the construction and staging space that will have the least impact on pedestrian, vehicular and bus traffic patterns, as well as disruption to other downtown business and parking on State Street and the Capitol Square. The trees impacted by construction and staging in W. Mifflin Plaza and Carroll St. will be replaced in kind with the exception of trees impacting new entries or loading docks to the project.

SECTION 3 – PHOTO DOCUMENTATION

Please attach photos. The group of photos must include:

- A photo to best depict the street tree relative to the proposed project.
- Date and timestamp of when photo was taken.

SIGNATURE CERTIFICATION

I hereby certify that I have presented an accurate and truthful representation of the proposed building and construction impacts to City street trees and a complete inventory of affected street trees and their condition herein, and that I will update this information and this report should any of this information change. I have worked to ensure compliance with all accepted professional standards in arboricultural practices and to ensure compliance with all applicable laws, regulations, policies and ethical standards. In the event the contractor has failed to comply with all applicable laws, regulations, policies and ethical standards; or created conditions that may present a hazard to people or property, I have immediately notified the appropriate representative of City of Madison Forestry Section at (608)266-4816.

CONSULTING ARBORIST SIGNATURE

ISA CERTIFICATION #

DEVELOPER APPLICANT SIGNATURE

DO NOT WRITE BELOW THIS LINE

CITY OF MADISON FORESTRY SECTION OFFICE USE ONLY:

CONSULTING ARBORIST REPORT

APPROVED REJECTED DATE: _____ REVISED DATE _____

CITY EMPLOYEE NAME _____

TITLE _____

SIGNATURE OF CITY EMPLOYEE _____

DEPOSIT REQUIRED \$ _____

LIST OF ADDITIONAL STREET TREE INVENTORY AND CONSTRUCTION IMPACT

STREET TREE NUMBER	Tree Species (Common Name)	Trunk Diameter (DBH)	Canopy Spread (Ft)	Trunk/Roots: General Structure/Health/Condition	Removal (R) Requested by Applicant? (Yes or No) *Photos required*	Pruning by City Forestry requested (Yes or No). Note: Any Pruning must follow ANSI A300 Standards.	What are the impacts of proposed building? i.e., construction, staging, underground vaults, concrete pumps, scaffolding, new underground utilities, etc.	What are the earth retention impacts to the street trees?
11	Gleditsia triacanthos variety (honey locust)	varied, 5"-8"	varied, 1 continuous canopy	In grade	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CONSTRUCTION, NEW UNDERGROUND UTILITIES, AND STAGING	N/A
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		
					<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input type="checkbox"/> No		



T 414.220.9840
75 N. Jefferson St.
Milwaukee, WI
53202

SMITHGROUP

144 E. Wisconsin St.
Suite 500
Milwaukee, WI 53202
602.511.1177
smithgroup.com

CONSULTANT:

NOTICE OF CONSTRUCTION
THESE DRAWINGS ARE PROVIDED FOR
THE USE OF LICENSED PROFESSIONALS ONLY.
REGULATED APPROVAL IS NOT
REQUIRED FOR THIS DRAWING.

State of Wisconsin
Division of Administration
Division of Facilities Development
30 N CARRIGAN ST, MADISON, WI 53703

EXISTING CONDITIONS - FREE INVENTORY



Title

MADISON, WISCONSIN

WISCONSIN HISTORICAL CENTER

WISCONSIN HISTORICAL SOCIETY

30 N CARRIGAN ST, MADISON, WI 53703

Drawing No.

Sheet No.

Page No.

Scale

Date

Type

Rev.

Date

Sheet No.

L001



1

NOTES:

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

Photos taken on 5/23/23 at approximately 4:00pm

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101



Photos taken on 5/18/23 at approximately 4:00pm

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260