

Review of Brearly Street Approaches to the Capital City Trail

Stop Condition for Brearly Street

Thursday, 8/20/2015, M. W. Rewey

70 degrees, mostly sunny

Brearily Street North Approach (Crosses Railroad Tracks)				
Time Increment	Total Approach Vehicles	Vehicles Not Stopping	% Not Stopping	Comment
1:30 - 1:45	11	3	27.3%	
1:45 - 2:00	3	0	0.0%	
2:00 - 2:15	7	0	0.0%	
2:15 - 2:30	9	0	0.0%	
2:30 - 2:45	14	2	14.3%	Semi cut-off bike after stopping*
2:45 - 3:00	9	0	0.0%	
3:00 - 3:15	14	0	0.0%	
3:15 - 3:30	8	1	12.5%	
3:30 - 3:45	6	1	16.7%	
3:45 - 4:00	10	1	10.0%	
2.5 hours	91	8	8.8%	* Only major problem. Most bicycles on path approached intersection with caution.

Brearily Street South Approach				
Time Increment	Total Approach Vehicles	Vehicles Not Stopping	% Not Stopping	Comment
1:30 - 1:45	8	0	0.0%	
1:45 - 2:00	11	0	0.0%	
2:00 - 2:15	9	0	0.0%	
2:15 - 2:30	15	0	0.0%	
2:30 - 2:45	6	0	0.0%	
2:45 - 3:00	16	1	6.3%	Came from MGE Parking Lot 200 feet to the south
3:00 - 3:15	13	0	0.0%	
3:15 - 3:30	11	0	0.0%	
3:30 - 3:45	13	0	0.0%	
3:45 - 4:00	6	0	0.0%	
2.5 hours	108	1	0.9%	Most bicycles on path approached intersection with caution.