

Attachment G. Interior and Exterior Photos of the Structure (Taken December 7th, 2023)



Photo 1. Southern side of building



Photo 2. Western porch and stairs of building



Photo 3. Eastern porch and entrance on CTY HWY AB



Photo 4. Northeast corner entrance and porch



Photo 5. North stairs and basement entrance



Photo 6. Main room on first floor, northern facing window



Photo 7. Emptied kitchen



Photo 8. Basement



Photo 9. Upstairs apartment



Photo 10. Molded support beams in upstairs storage, "knob and tube" wiring remnant