



Area of Masonry Repair

Garner Masonry Repairs- 2013

Area of Masonry Repairs




Garner Park Masonry Repairs-2013

Area of Masonry Repair



Garner Park Masonry Repairs- 2013



Mortar separating from stone allowing excessive moisture to penetrate, causing excessive freeze thaw cycles and leading to deteriorating mortar joints

Improper repair with caulk holding in moisture

Previous repairs failing due to improper mortar selection.

Soft joints added above flashing not allowing proper drainage

Garner Park Masonry Repairs- 2013  
Typical Condition of Masonry Mortar Joints in Designated Repair Areas