



Figure 15 - Dining room area showing damaged ceiling tile on interior of the Chi Chi's Restaurant building.



Figure 16 - Bar area showing damaged ceiling tile on interior of the Chi Chi's Restaurant building.



Figure 17 - Prep kitchen area between dining room area and kitchen showing service door on south side of facility building.



Figure 18 - Main kitchen area of the Chi Chi's Restaurant building.



Figure 19 - Main kitchen area of the Chi Chi's Restaurant building showing walk in freezer in background.



Figure 20 - Ice machines and water softener showing back door leading to dumpster storage area in the southwest corner of Chi Chi's Restaurant building. Door to utility room on right.



Figure 21 - Electric control panels in utility/storage room.



Figure 22 - Water heaters in small room adjacent to kitchen area.





























