

Bailey, Heather

From: Kurt Hartjes <kurt@waunakeeremodeling.com>
Sent: Monday, August 05, 2019 5:33 PM
To: Bailey, Heather
Subject: FW: Miller
Attachments: IMG_1035.jpg; ATT00001.txt; IMG_1036.jpg; ATT00002.txt; IMG_1037.jpg; ATT00003.txt; IMG_1038.jpg; ATT00004.txt

Hi Heather,

Here are the pictures I took for #111 and #112. #111 is rotted on the sill and doesn't seal at all, and #112 is boarded up on one side because it is broke. The same window is going into those two. Changing from a double hung unit to an awning unit. I will be sending you the mock up in a separate email so you see they are the best match instead of the old double hung submission.

Kurt Hartjes
Sales Manager
Waunakee Remodeling
608-850-2127
www.waunakeeremodeling.com

-----Original Message-----

From: Kurt Hartjes <kurt@waunakeeremodeling.com>
Sent: Monday, August 05, 2019 5:19 PM
To: Kurt Hartjes <kurt@waunakeeremodeling.com>
Subject: Miller












Renewal
by Andersen.
WINDOW REPLACEMENT



111 Living Room

Window - 34.00W x 29.00H



EXTERIOR



INTERIOR

