

1359 House Photos



Exterior (West Side)



Exterior (North Side)

1359 House Photos



Exterior Back Yard (East Side)



Exterior (South Side)

1359 House Photos



Garage Door - frame not plumb due to structure settlement

1359 House Photos



Basement stairs on east side of house



Basement stairs and canopy

1359 House Photos



Kitchen



Kitchen floor sloping to left in photo

1359 House Photos



Living room



Bathroom
Page 6 of 9

1359 House Photos



Garage floor



Garage floor - settlement about 3-1/2"

1359 House Photos



Basement



Basement floor/wall joint - note floor settlement

1359 House Photos



Basement



Basement floor/wall joint - note floor settlement