



View West between 120 & 124 North Hancock



View from the South West of 119, 123 & 125 North Butler



View from the North East (Rear) of 119, 123 & 125 North Butler



View from the South East (Rear) of 119, 123 & 125 North Butler
119, 123 & 125 North Butler Existing Exterior Conditions
May 5, 2007



View from North West



View from South West




View from North East



View from South East



Basement



Stair




East/Common Entry



South Unit Kitchen




South Unit Hall/Bedroom



South Unit Living Room




North Unit Living/Bed Room




North Unit Kitchen




South Unit Bedroom



View from North West



View from South West



View from South West



View from North East



View from South East



View from South East




Basement




First Floor Kitchen



First Floor Hall/Living Room



First Floor Living Room



Stair Up to Third Floor




Second Floor Hall



Second Floor Kitchen



Second Floor Living Room



Third Floor Bedroom



Third Floor Hall



Stair Down to Second Floor



Second Floor Bedroom