Traffic Customer Registration Report

LOCATION:I-35 AT FM	Landmarks Construction			Weather/Pavement Condition		Page
Date	Name	Activity		Air Temp	Pave Temp	No
Station Offset Roadway Impacts Description - MAP						
1 Station: 1+00 Offset: 0 Roadway: Frontage Road Direction: Eastbound	Staff	Lane closure on Frontage Road	1 - Flagman 1 - Truck w/ Arrow Board	75 - Clear	75 - Dry	
		Flagger: Jaquez, Jonathan A Operator: Jaquez, Jonathan A				
Working Hours						
Working Hours Log						
Name	**Classification**					
1 - Jaquez, Jonathan A	Construction Flagger					
2 - Ramirez, Ruben	Construction Worker					
3 - Ramirez, Ruben	Construction Worker					