













ST03A

-  Greenway
-  Pond
-  Ponds in TMDL Model (2)
-  Stormwater Pipes
-  Private Pipes
-  Excluded Pollutants (1)
-  PD 6821-006_EXP
-  PD 6821-006_MAD
-  PD 7020-084_EXP
-  PD 7020-084_MAD
-  SS7129-021_EXP
-  SS7129-021_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded




Date: 2/19/2021



ST03B



- Greenway
- Pond
- Ponds in TMDL Model (3)
- Catchbasins (4)
- Stormwater Pipes
- Private Pipes
- Excluded Pollutants (1)
- Autumn_Lake_EXP
- Autumn_Lake_MAD
- PD 6829-013_EXP
- PD 6829-013_MAD
- PD 7028-006_EXP
- PD 7028-006_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded





















Date: 2/19/2021






ST04

-  Greenway
-  Pond
-  Ponds in TMDL Model (5)



- | | | |
|---|---|---|
|  Stormwater Pipes |  PD 6832-008_EXP |  PD 7031-007_MAD |
|  Private Pipes |  PD 6832-008_MAD |  PD 7032-012_EXP |
|  Excluded Pollutants (1) |  PD 6834-021_EXP |  PD 7032-012_MAD |
|  PD 6831-055_EXP |  PD 6834-021_MAD |  SS6733-038_MAD |
|  PD 6831-055_MAD |  PD 7031-007_EXP |  SS6733-039_MAD |

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded











Date: 2/19/2021






ST05B



-  Pond
-  Ponds in TMDL Model (2)
-  Stormwater Pipes
-  Private Pipes
-  Excluded Pollutants (1)
-  ESideWalmart_MAD
-  PD 6535-008_EXP
-  PD 6535-008_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded
















Date: 2/19/2021






ST05A

-  Greenway
-  Pond
-  Ponds in TMDL Model (4)



-  Stormwater Pipes
-  Private Pipes
-  Excluded Pollutants (1)
-  PD 6738-024_EXP
-  PD 6738-024_MAD
-  PD 6836-018_EXP
-  PD 6836-018_MAD
-  PD 6935-077_MAD
-  PD 7036-027_EXP
-  PD 7036-027_MAD



Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded




Date: 2/19/2021





ST06A

- Greenway
- Pond
- Ponds in TMDL Model (3)
- Catchbasins (1)
- Stormwater Pipes
- Private Pipes
- Excluded Pollutants (1)
- PD 6748-011_MAD
- PD 6942-013_MAD
- PD 7143-001_EXP
- PD 7143-001_MAD
- PD 6748-011_EXP

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded



Date: 2/19/2021




ST06B

- Greenway
- Pond
- Ponds in TMDL Model (4)



- Stormwater Pipes
- Private Pipes
- Excluded Pollutants (1)
- PD 6444-019_EXP
- PD 6444-019_MAD
- PD 6544-013_EXP
- PD 6544-013_MAD
- PD 6546-029_EXP
- PD 6546-029_MAD
- PD 6645-041_EXP
- PD 6645-041_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded



Date: 2/19/2021






ST07



- Greenway
- Pond
- Ponds in TMDL Model (5)

- Stormwater Pipes
- Private Pipes
- Street Sweeping (1)
- Excluded Pollutants (1)
- GR 6039-093_MAD
- GR 6039-093_Sw_EXP
- GR 6039-093_Sw_MAD
- PD 5622-036_EXP
- PD 5622-036_MAD
- PD 5730-043_EXP
- PD 5730-043_MAD
- PD 6034-016_EXP
- PD 6034-016_MAD
- PD 6423-015_MAD

Note:
 _Sw =more frequent sweeping
 _Exp = excluded pollutants
 _Mad =not excluded



Date: 2/19/2021




ST08

- Greenway
- Pond
- Ponds in TMDL Model (2)



- | | | |
|-----------------------|-------------------------|-----------------|
| Private Practice (50) | Street Sweeping (1) | PD 6438-016_EXP |
| Catchbasins (34) | Excluded Pollutants (1) | PD 6438-016_MAD |
| ScreenStructures (3) | NA_SC_EXP | PD 6438-017_EXP |
| Stormwater Pipes | NA_SC_MAD | PD 6438-017_MAD |
| Private Pipes | NA_SC_Sw_MAD | |

Note:
 _Sw =more frequent sweeping
 _Exp = excluded pollutants
 _Mad =not excluded



Date: 2/19/2021








UY01

- | | | | |
|-------------------------|-------------------------|-----------------|-----------------|
| Greenway | Private Practice (3) | NA_UY_MAD | PD 5219-011_MAD |
| Pond | Catchbasins (8) | PD 5020-054_EXP | PD 5417-009_EXP |
| Ponds in TMDL Model (4) | Stormwater Pipes | PD 5020-054_MAD | PD 5417-009_MAD |
| | Private Pipes | PD 5119-009_MAD | PD 5219-011_EXP |
| | Excluded Pollutants (1) | | |




Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded














Date: 2/19/2021




WA01



-  Greenway
-  Pond
-  Ponds in TMDL Model (5)

-  Stormwater Pipes
-  Private Pipes
-  Excluded Pollutants (1)
-  PD 6968-017_EXP
-  PD 6968-017_MAD
-  PD 7068-001_EXP
-  PD 7068-001_MAD
-  PD 7069-001_MAD
-  PD 7168-035_MAD
-  PD 7169-044_EXP
-  PD 7169-044_MAD




Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded















Date: 2/19/2021




WA02

-  Greenway
-  Pond
-  Ponds in TMDL Model (4)


-  Private Practice (5)
-  Stormwater Pipes
-  Private Pipes
-  Excluded Pollutants (1)
-  NA_WA_MAD
-  PD 6965-001_EXP
-  PD 6965-001_MAD
-  PD 6965-002_MAD
-  PD 7065-029_EXP
-  PD 7065-029_MAD
-  PD 7067-014_EXP
-  PD 7067-014_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded




Date: 2/19/2021
















Document Path: M:\MS4_WaterQualityModel\2019_2020 Modeling Effort\GIS\WorkingMXDs\ModelAreas_DD.mxd
 User Name: enles




WA03



-  Greenway
-  Pond
-  Ponds in TMDL Model (4)

-  Stormwater Pipes
-  Excluded Pollutants (1)
-  NA_MudLake_MAD
-  PD 6966-001_MAD
-  PD 6966-002_EXP
-  PD 6966-002_MAD
-  PD 6967-034_MAD
-  PD 6967-035_MAD












Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded




Date: 2/19/2021



WC01



-  Greenway
-  Pond
-  Ponds in TMDL Model (1)
-  Private Practice (26)
-  Catchbasins (24)
-  ScreenStructures (1)
-  Stormwater Pipes
-  Private Pipes
-  NA_MENWC_MAD
-  PD 3456-032_MAD
-  SS4151-093_MAD

Note:
 _Sw =more frequent sweeping
 _Exp = excluded pollutants
 _Mad =not excluded















Date: 2/19/2021






WI01



-  Greenway
-  Pond
-  Ponds in TMDL Model (1)

-  Catchbasins (5)
-  Screen Structures (2)
-  Stormwater Pipes
-  Private Pipes
-  Street Sweeping (1)
-  PD 4059-045_MAD
-  SS4255-083_MAD
-  SS4257-098_MAD
-  SS4455-152_Sw_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded




Date: 2/19/2021



WI02A



- Greenway
- Pond
- Ponds in TMDL Model (1)
- Private Practice (6)
- Catchbasins (12)
- ScreenStructures (2)
- Stormwater Pipes
- Private Pipes
- Street Sweeping (1)
- Excluded Pollutants (1)
- NA_WI_MAD
- PD 4664-013_EXP
- PD 4664-013_MAD
- PD 4664-013_Sw_EXP
- PD 4664-013_Sw_MAD
- SS4565-037_MAD

Note:
 _Sw =more frequent sweeping
 _Exp = excluded pollutants
 _Mad =not excluded










Date: 2/19/2021






WI02B

-  Greenway
-  Pond

-  Private Practice (8)
-  Catchbasins (6)
-  ScreenStructures (1)
-  Stormwater Pipes
-  Private Pipes
-  Street Sweeping (1)
-  NA_WI_Sw_MAD

Note:
 _Sw = more frequent sweeping
 _Exp = excluded pollutants
 _Mad = not excluded



Date: 2/19/2021

