

Olbrich Garden Roof Detail 'As Built' Drawing

This vapor barrier does not exist as shown. Rather it resembles a polypropylene tarp material that was fastened to the underside of the perlin. Thus with deterioration, there is no vapor barrier.

