

**1355 House Photos**



Exterior (West Side)



Exterior (North Side)



**1355 House Photos**



Exterior Back Yard (East Side)



Exterior (South Side)





Exterior Foundation Settlement and Movement Repairs

1355 House Photos



Kitchen



Living Room





Bedroom closet - Floor settlement gap between floor and baseboard



Bathroom

1355 House Photos



Basement - note floor crack



Basement - note floor crack



1355 House Photos



Basement - note floor slope along wall, carpet covering floor.



Supplemental floor support added - note separation of wall from ceiling. Door frames are racked and doors swing open.

**1355 House Photos**



Foundation wall crack



Foundation wall and ceiling cracks