



Current Conditions - Exterior - Lakefront Facade

DELTA UPSILON


CHAPTER HOUSE RENOVATION



Current Conditions - Exterior - Lakefront Facade

DELTA UPSILON

CHAPTER HOUSE RENOVATION



Exterior Elevation - South and East

DELTA UPSILON


CHAPTER HOUSE RENOVATION



Exterior Elevation - North and West

DELTA UPSILON

CHAPTER HOUSE RENOVATION




DELTA UPSILON


CHAPTER HOUSE RENOVATION

1960's Renovation

1



2




Floor Plans


DELTA UPSILON

CHAPTER HOUSE RENOVATION

3/4



5



Floor Plans

DELTA UPSILON

CHAPTER HOUSE RENOVATION



Proposed Front Entry

DELTA UPSILON
CHAPTER HOUSE RENOVATION



Proposed - Addition to First Floor Dining Room


DELTA UPSILON
CHAPTER HOUSE RENOVATION



Historical and Current Conditions - Living Room

DELTA UPSILON

CHAPTER HOUSE RENOVATION



Historical and Current Conditions - Trophy Room

DELTA UPSILON

CHAPTER HOUSE RENOVATION



Proposed Design - Trophy Room

DELTA UPSILON
CHAPTER HOUSE RENOVATION



Proposed Design - Living Room

DELTA UPSILON
CHAPTER HOUSE RENOVATION