








Project Location - Parking Lots 129 & 130



Existing Conditions – Parking Lots 129 & 130

Lot 129

- Gravel Parking Surface
- 28 total parking stalls (not marked)
- Payment required for parking via kiosk
- Tendency to flood during heavy rains
- Existing vegetation along bike path
 - mowed bluegrass lawn & canopy trees
- Existing vegetation along wetland/shoreline
 - Woody pioneer species

Lot 130


- Gravel Parking Surface
- 93 total parking stalls (not marked)
- Payment required for parking via kiosk
- Existing vegetation around parking lot
 - mowed bluegrass lawn & canopy trees predominately Ash







Existing Conditions – Parking Lots 129 & 130




Proposed Improvements – Lots 129 & 130

Lot 129

- Deconstruct parking lot and remove gravel
- Add paved surface for bike parking

Lot 130


- Reconstruct Parking Lot (Revised Layout)
- Asphalt surface with curb and gutter only around interior basin and entrance
- 100 total parking spaces
 - 96 regular stalls / 4 ADA stalls
- Bioretention for stormwater management
- Compatible with future UW-Madison concepts
- Enhanced pedestrian crossing



Revised Layout – DRB Preview (July 2018)



Proposed Layout – Lot 130






Impacts to Wetlands



Planting and Landscape Restoration – Lot 130



Planting and Landscape Restoration – Lot 129

