

WAUNAKEE REMODELING, INC.

Ken Miller

5510 Greenleaf Drive

Madison Wi. 53713

608-695-6886

kenm5501@aol.com

1001 Frank H. Street • Waunakee, WI 53597
Phone: 608/849-5155 • FAX: 608/849-9335

5960 Odana Road • Madison, WI 53719
Phone: 608/442-0032 • FAX: 608/442-0058

Property address. 15 East Gilman #7. Madison Wi. 53703

#101. Bath- Missing the bottom sash. Rot in lower frame. No pulleys. No weights. Bottom sash needs to be tempered.

#102. Kitchen- Missing lower sash. Rot in lower frame. No weights.

#103. Kitchen- Missing lower sash. Rot in lower frame. No pulleys. No weights.

#104. Pantry- Missing lower sash. No pulleys. No weights.

#105. Pantry- Missing lower sash. No pulleys. No weights.

#106. Bed 1. Missing lower sash. Rot in lower frame. No pulleys. No weights.

#107. Bed 1. Missing lower sash. Rot in lower frame. No pulleys. No weights.

#108. Bed 1- No glass in lower sash. Rot in lower frame. No pulleys. No weights.

#109. Bed 2- No glass in lower sash. Unit is out of square. Sashes will not operate. No pulleys. No weights.

#110. Bed 2- Unit is out of square. Sashes will not operate. No pulleys. No weights.

#111. Front- Existing is just a sash with hinges. Out of square. Missing hardware. Wont seal.

#112. Front- Existing is just a sash with hinges. Out of square. Missing hardware. Wont seal. Rot in lower sash. Missing storm window.

#113. Bed 3- Missing lower sash. Rot in lower frame. No pulleys. No weights.

#114. Bed 3-. Missing lower sash. Rot in lower frame. No pulleys. No weights.

Gary Buhler.

"We Make Everything Old Look New Again"







101









102

103















105










106














108



108





109




109



110








110











112



112



113







114



114

